## Work Order ID 65228

January 10, 2011 9:49:45 AM

Page 1

Insp.

Stamp

Item ID: D3394-3 Accept Setup Start **Revision ID:** Stop Item Name: Lug Start Qty: 4.00 **Start Date:** 1/10/11 **Cust Item ID:** Req'd Qty: 4.00 Required Date: 1/14/11 **Customer:** Reference: Start Run Process Plan: **Tooling:** Approvals: Date: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ **Tool ID** Tool # Plan Reject Accept Reject **Work Center ID** Description Number **Qty** Qty **Run Hours** Code **Draw Nbr Revision Nbr** D3394 DEO \*--Rev B 100 0.00 M 11 01 Small Fab 0.00 Memo Small Fab 1 X D3394-043 B **6258** REMOVE GROMMETS TO RE-STOCK AS D3394-3

110

Packaging

Packaging

0.00

Memo

**RE-STOCK** AS D3394-3---

Identify as per dwg & Stock Location:

11.01-20 G

## Work Order ID 65228



Page 2

January 10, 2011 9:49:45 AM

Item ID:

D3394-3

**Revision ID:** 

Item Name:

Lug

1/10/11 **Start Date:** Required Date: 1/14/11

Start Oty: 4.00 Req'd Oty: 4.00

Accept

Setup Start

Stop

Reference:

Approvals:

Process Plan:

Date:\_\_\_

Date:

Tooling:

SPC (Y/N):

Set Up/

Date: Tool ID

Date:

Tool # Plan

Code

**Cust Item ID:** 

Customer:

Run

Start

Sequence ID/

Work Center ID

120 \*

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Memo

Run Hours 0.00

0.00

Accept

Qty

Reject

Stop

Reject

Number

Insp. Stamp

MP 11-01-24

January 10, 2011 9:49:44 AM

Work Order ID: 65228

Parent Item:

D3394-3

Parent Item Name: Lug



**Start Date: 1/10/11** 

Required Date: 1/14/11

Start Qty: 4.00

Required Qty: 4.00

**Comments:** 

New Issue 11/01/10 LL

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3394-043		Manufactured	No				Each	91.0000	1	4			

Lug Assembly

Location	Loc Qty	Loc Code	
ST420	7		<u> </u>
62589	7		
ST475	84		
.62005	6		
62667	8		
62930	40		
62976	30		